


PR2 Gear Pumps with Relief Valve



Symbol



How to order

PR2+LV20A64	F	3	R	X	2B
Gera pump with relief valve	Mounting F: Flange type	Displacement (L/min) 1, 2, 3, 4, 6, 8	Rotation direction R: CW L: CCW	Shaft type X: Flat shaft Y: Tooth spline shaft	Flange mounting type 2B: 2 JIS blot 4BJ: 4 JIS bolt 4DE: European 4-bolt